


Coaxial Probe Test Charts

Coax Probe Isolation



Variable

VF -CH

Linear Sweep

Start -100.00V
Stop 100.00V
Step 1.0000V

Constants:

V -CH3 -100.00V

